



**ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ-1, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,
ਭਵਨ ਤੇ ਮਾਰਗ, ਸਾਖਾ, ਮਲੇਰਕੋਟਲਾ**

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ,
Wosdom World School, Dehliz Raod,
Ahmedgarh.

ਨੰਬਰ **28** ਮਿਤੀ **23-04-2024**
ਵਿਸ਼ਾ: ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਸਬੰਧੀ।

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ: WWS/2024-25/83, ਮਿਤੀ: 06-04-2024 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦਫਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਸ੍ਰੀ ਬਲਪ੍ਰੀਤ ਸਿੰਘ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2024-25 (31-03-2025) ਤੱਕ ਬਾਹਰੋਂ ਦੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ੀਨਲ ਅਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਜੇਕਰ ਹੜ, ਕੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਹਾਂ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾਉਣ ਉਪਰੰਤ ਤਸਦੀਕ ਵੀ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਇਸ ਦਫਤਰ ਵੱਲੋਂ ਜੀ.ਆਰ. ਨੰਬਰ 664168, ਮਿਤੀ 22-04-2024 ਰਾਹੀਂ 10,000/ ਜਮਾਂ ਕਰਵਾ ਲਈ ਹੈ। ਇਸ ਦੇ ਨਾਲ ਹੀ ਸਬੰਧਿਤ ਸਕੂਲ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਰਹਿੰਦੇ ਸਰਟੀਫਿਕੇਟ ਇਸ ਦਫਤਰ ਵਿੱਚ ਜਮ੍ਹਾਂ ਕਰਵਾਉਣੇ ਯਕੀਨੀ ਬਣਾਏ ਜਾਣ। ਜਿਸ ਕਾਰਨ ਇਸ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਨੂੰ ਆਰਜੀ ਤੌਰ ਤੇ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਨੱਖੀ/ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ : 1 ਲੋ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸਾਖਾ ਮਲੇਰਕੋਟਲਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ-

ਮਿਤੀ-

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ, ਭ ਤੇ ਮ ਸਾਖਾ, ਮਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ : 1 ਲੋ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸਾਖਾ ਮਲੇਰਕੋਟਲਾ।

**Name of School:-Wisdom World School, Dehliz Road,
Ahmedgarh**

As per report by Sh Balpreet Singh junior Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:-

1. However, the Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained be from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the building as per Drawing submitted by the owner.
8. This report is not valid for legal purpose.

As per visually inspection as reported by the undersigned the above building may be used for normal use for One year up to 31/03/2025 subject to the above conditions.


Sub-Divisional Engineer,
Const. Sub Division no 1 ,
PWD B&R Malerkotla.
